

ANTI SMITH
12660/LAB12660

QUICK REFERENCE

Due to an assay reagent issue, performance of the Anti Smith assay has been temporarily suspended at Allina Health Laboratory

DETAILS

Until a thorough investigation of the reagent issue can be completed, all requests for Anti-Smith antibody testing should be ordered as a Miscellaneous Send Out (994/LAB994, MSO) indicating that Anti-Smith antibody testing is requested. The sample will be routed to LabCorp for testing.

QUESTIONS: Contact your Allina Health Laboratory account representative, or our Client Services department